


SPOJENÉ TOVÁRNY NA OBRÁBĚCÍ STROJE — NÁRODNÍ PODNIK




OH 4

2



$m 1 - 2,5$



$$\frac{Z}{Z_n} = \frac{A}{B} \times \frac{C}{D}$$

| Z | A | B | C | D | Z | A | B | C | D |
|-----|----|----|----|----|-----|----|----|----|----|
| 102 | 51 | | 80 | 40 | 148 | 74 | | 80 | 40 |
| 104 | 52 | | 80 | 40 | 150 | 50 | | 90 | 30 |
| 105 | 70 | | 72 | 48 | | | | | |
| 108 | 54 | | 80 | 40 | | | | | |
| 112 | 56 | | 80 | 40 | | | | | |
| 116 | 58 | | 80 | 40 | | | | | |
| 120 | 60 | | 80 | 40 | | | | | |
| 123 | 41 | | 90 | 30 | | | | | |
| 124 | 62 | | 80 | 40 | | | | | |
| 126 | 84 | Zn | 72 | 48 | | | Zn | | |
| 128 | 64 | | 80 | 40 | | | | | |
| 129 | 43 | | 90 | 30 | | | | | |
| 132 | 66 | | 80 | 40 | | | | | |
| 135 | 45 | | 90 | 30 | | | | | |
| 136 | 68 | | 80 | 40 | | | | | |
| 138 | 46 | | 90 | 30 | | | | | |
| 140 | 70 | | 80 | 40 | | | | | |
| 141 | 47 | | 90 | 30 | | | | | |
| 144 | 72 | | 80 | 40 | | | | | |
| 147 | 49 | | 90 | 30 | | | | | |