

Sheet2

stoupání	A	B	C	D	kontrola	kontrola reálný - nastavený
50	30	100	44	65	1	0.00012307692308
48	30	96	44	65	1	0.00012820512821
44	30	88	44	65	1	0.00013986013986
40	30	80	44	65	1	0.00015384615385
38	30	76	44	65	1	0.00016194331984
36	30	72	44	65	1	0.00017094017094
32	30	64	44	65	1	0.00019230769231
28	30	56	44	65	1	0.00021978021978
24	30	48	44	65	1	0.00025641025641
20	30	40	44	65	1	0.00030769230769
19	30	38	44	65	1	0.00032388663968
18	40	48	44	65	1	0.00034188034188
16	45	48	44	65	1	0.00038461538462
14	36	42	55	65	1	0.00043956043956
12	30	30	55	65	1	0.00051282051282
11	48	44	55	65	1	0.00055944055944
10	48	40	55	65	1	0.00061538461538
9	48	36	55	65	1	0.00068376068376